

## MEMORANDUM

PREPARED FOR: Sylvia Burges/EPA Region 10

DATE:

December 10, 1996

**COPIES TO:** 

Edwin Liu/RP Paul Nemanic/RP

Ed Petrie/RP

Fred Ellerbusch/RP Rich Torrito/RP John Abrams/RP Tom McLaughlin/RP Mike Shatynski/RP Betsy Carlton/RP Buzz Rahier/RP

Sue Hays/Hays Consulting

Chuck Blumenfeld/Bogle & Gates

Doug Holsten/CH2M HILL Howard Steeley/Ecology Theresa Michelsen/Ecology

Pam Elardo/Ecology Peter Wright/Monsanto Rene Fuentes/EPA

# TECHNICAL STATUS REPORT

**CHAM** HILL

PREPARED FOR: Sylvia Burges/EPA Region 10

COPIES TO: Byung Maeng/Ecology

PREPARED BY: Liz Luecker/CH2M HILL

DATE: December 10, 1996

**SUBJECT:** Rhône-Poulenc Monthly Status Report

SITE NAME AND

LOCATION: Rhône-Poulenc Inc./Seattle Plant

Tukwila, WA

REPORTING

**PERIOD:** November 1 through November 30, 1996

**PROJECT:** 136734.P1.ZZ

Following is CH2M HILL's technical status report summary for the RCRA Corrective Action Project at Rhône-Poulenc's (RP) Seattle Plant. This status report summarizes activities implemented and planned for this Corrective Action project and is intended to be transmitted to U.S. EPA Region 10 in fulfillment of the monthly progress reports required in Consent Order No. 1091-11-20-3008(h).

## **Progress Made This Reporting Period**

# Task P1-Project Management

The EPA status report was faxed to EPA on November 8 and mailed to the distribution on the same day.

Edwin Liu/RP met with Sylvia Burges/EPA 10 on November 21 to discuss the site, preparation of the Risk Assessment/Media Cleanup Standards, and the Round 3 Technical Memorandum submittal.

## Task A3-Interim Measures

## Report.

A report documenting the compressor pad excavation, the PCB ditch excavation, sewer cleaning, and disposal of associated waste streams is currently being developed by Terra Nova Environmental Sciences and CH2M HILL.

November 1996 Status Report Rhône-Poulenc Inc Seattle Plant

### LNAPL.

RP monitored the wells for LNAPL on November 30. The wells monitored for LNAPL were: H10, H11, H9, G3, MW-14, MW-15, MW-17, MW-18, MW-19, and MW-20. Wells MW-12, DM-7, and B6 were not accessible at this time because containers belonging to Northwest Container were stored on top of the wells. No well monitored contained a measurable amount of LNAPL. The samples from wells H10, H11, and MW-15 had sheens, and the sample from MW-19 had a slight sheen. The remaining wells surveyed did not contain LNAPL. Information on the LNAPL thicknesses is attached.

### Task A8-Round 3 Technical Memorandum

Sylvia Burges/EPA 10 sent Edwin Liu/RP a letter dated November 5, 1996, approving the Round 3 Technical Memorandum, pending submittal of the revised insert pages and submittal of the sediment data to Ecology. The letter also directed RP to start preparation of the Risk Assessment/Media Cleanup Standards report.

# **Deliverables Submitted**

The October Progress Report was submitted to U.S. EPA on November 8.

# Progress Planned For Next Reporting Period

# Task A2-Applicable Regulations and Permits

### Leasing Arrangements.

The PCB ditch area will be paved by Lakeridge Paving once excavation of contaminated soils is complete and EPA approves the Interim Measures report.

The soil and shrubbery Northwest Container Services' contractor removed from the area near the Facility's North Road, near the entrance (in RFI investigation Areas BG and A3) and from south of the laboratory building (in Area A3) is still being stockpiled on site. The soil was placed in two dirt piles (approximately 10 cubic yards) located at the northwest corner of the laboratory building and a third pile located southwest of the laboratory building (approximately 100 cubic yards). Northwest Container will dispose of this soil as non-hazardous based on past sampling data.

November 1996 Status Report Rhône-Poulenc Inc Seattle Plant

## Task A3-Interim Measures

## LNAPL.

During the November 21 meeting, EPA and RP agreed that LNAPL would no longer be monitored on a monthly basis.

# Task S1-Miscellaneous Field Support

# Drum Disposal.

A total of 13 drums of wastes are on site. The wastes include:

- 11 partial drums of wash water from cleaning the API separator and the storm water tank, and
- 2 drums of used activated carbon

The remaining water in the drums contains higher concentrations of sediments. This water will be transferred to the mobile holding tank and filtered through one-micron filters. The filtrate will be analyzed for copper by Sound Analytical and discharged to Metro.

# Outfall 4 Wash Water in Aluminum Tank.

Approximately 1,000 gallons of outfall 4 wash water and sludge are in the aluminum tank. The water in the aluminum tank will be filtered on site through one-micron filters and discharged to Metro, provided it meets Metro's discharge parameters. Filtration of the water is expected to occur during December/January. Sludge in the tank will be removed, solidified, and landfilled at the Waste Management, Inc., hazardous waste facility in Arlington, OR.

rhône-p/MSR/11-96EPA

# RHONE POULENC - MARGINAL WAY FACILITY MONTHLY LNAPL SURVEY LOG Floating Product Layer Thickness in Feet

ļ									,							<del></del>				,		<del>,</del>	<del></del>	<del>,</del>	<del></del>				<del></del>		<del></del>				<del>,</del>	<del>,</del>		
Date	****	FT 1	MW12	***	D.4.	***	1 77	DM2A	DM2B	DM8	A9	DM3A	DM3B	A2		DMA	B4	D2	DM5	DIA	RIP	C1	DM	B5	- G3	G1	204	MWIZ	MOVE	NAME OF	MANA	Maria	NOVICE	100000	Name of	DM1A	1	
	H10 0	HI	0	Hii	DM7	Н9	Н6	DMZA	DMZB	DM9	A9	DWISA	DMSB	AZ	A4	DIVIA	D4	DZ	DIVIS	DIA	BIB	CI	DIVIO	Б3	GS	GI	D0	1414413	NIW 14	MW15	MW16	MW17	MW18	MW19	MWZU	DMIA	DMIB	E3
	0		0				-		<del> </del>	<del> </del>					<del> </del>	<del>                                     </del>		<del>                                     </del>	+			-	<del>                                     </del>	<del> </del>	<del>                                     </del>	<del>                                     </del>	<del>                                     </del>	<del> </del>	<del>                                     </del>	<del>                                     </del>	<del> </del>		<del> </del>	<del> </del>	<del></del>	<del></del>	<del></del>	<del></del>
	Film	0	0.007	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1 0	0	0	0	0	0	0	0	0		<del></del> -	<del>                                     </del>	<del> </del>	-	<del> </del>	<del> </del> -		<del></del>		<del></del>
	Film	Sheen	Sheen	Film	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		<del></del>	<del> </del>			<del>                                     </del>	<u> </u>		<del> </del>		
	Film	0	Film	0.01	ō	Sheen	Sheen	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.021	0.005	0	0	0.01	0			
	0	0	Sheen	0.01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	NA	0	0	0	0	0	Sheen	0	0	0	0.021	0			
11/3/94	0	0	0.005	0.005	0	0	0	0	0	0.	0	0	0	0	0	0	0	0	0	0	0	0	0	NA	0	0	0	0	0	0.01	0	0	0		0			·
12/5/94	0	0	0	Sheen	0	0,	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	NA	0	0	0	0	0	Sheen	0	0	0	0	0			·
1/11/95	0.26 ª	Sheen	Sheen	0.04 <sup>d</sup>	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	NA	0	0	0	0	0	0.01 a	0	0	0	Sheen	0			
2/17/95	2.01	0	0.16	Sheen	0	0	0	0	0	0	NA	0	0	0	0	0	0	0	Ор	0	0	0	0	NA	0	0	0	0	0	0	0	0	Sheen	Sheen	0			
3/23/95	0.01										0	0	0	0	0°					0	0	0														0	0	Sheen c
3/27/95		0	Sheen	0	0	0	0	0	0	0						0	0	0	0		1		0		0	0	0	0	0	Sheen	0	0	Sheen	Sheen	0			
3/28/95																								0														
4/27/95	0.063	0	Film <sup>d</sup>	0		0				0	0	0	0	NA	0		0	0	0	0	0	0	0	0	0	0	0	0	0			0	0.063 °	Sheen	0		T	
4/28/95					0		0	0	0 .							0			<u> </u>	<u> </u>	<u> </u>		<u> </u>		ļ					0	0							
5/31/95		0	Film	0	0	0	0	0	0	0	0	0	0	NA	0	0	0	0	0	0	0	0	0	0	0.	0	0	0	0	0	0	0	0	0	0			
6/30/95 SI	heen d	0	Film	NA	0	0	0	0	0	0	0	0	0	NA	0	0	0	0	0	0	0	0	0	0	0	0	0	NA	Sheen	Sheen	0	0	Sheen	0	0		T	]
7/28/95																	0			0		0	0	0				0	0						0			
7/29/95 S		0	Sheen	NA	0	0	0	0	0	0	0	0	0	NA	0	NA		0	0		NA				0	0	0			0	0	0	0	0				
8/26/95 S		0	Sheen	0	0	0	0	0	0	0	0	0	0	NA	0	NA	0	0	0	0	0	0	0	NA	0	0	0	0	0	0	0	0	0	Sheen	0			
9/29/95	0.03	0			0	0	0	0	0	0	0	0	0	0	0	0		0	0	0	0	Sheen	0	0	0	0	0		0	0	0	0	0	Sheen	0			
10/4/95			Sheen d	d													0				<u></u>	ļ						0					]					
10/30/95	0.03	0	d	Film	0	0			1			0	0	0	0	0	0	NA	NA		0	0	0	0	0	NA	0	0	0	0	0	0	0	0	0 f	T	T	
10/31/95							0	Sheen	Sheen	0	0							NA .	NA	0						NA												
11/30/95	Film	0	Sheen	Film	0	0	0	0	0	0	0	0	0	0	0	0	0	0	NA	. 0	0	0	0	0	0	NA	0	0	0	0 -	0	0	0	Sheen	0			
12/31/95	0.2	0	Film	Sheen	NA	0	0	0	0	0	0_	0	0	0	0	0	0	0	0	0	0	0	NA	NA	0	NA	NA	0	0	Sheen	0	0	0	0	0			
1/3/96	1.17		d	Sheen	0	0																	_		0		NA		0	0		0	Sheen	0	0			
2/27/96 F	Film <sup>g</sup>		0	Sheen	0	- 0																			0		0		0	0		01	0.09	0	$0_{\rm t}$			
	Film		Film	Film	0	0			1																0		NA		0	Sheenh		0	0	Sheen	0,			
	Film		d	Sheen	0	0																			0		NA		0	0		0	Sheen	Sheen	0			
	Film		d	Sheen <sup>h</sup>	0	0																			0		NA		0	0		0	0	0	0			
	Film		Sheend		NA	. 0																			0		0		0	0		0	0	0	0			
	Film		Film	Film	NA	0													<u>  </u>		<b> </b>				0		0		0	Sheen		0	0	0	0			
8/31/96 S	heenh		Film	Sheen <sup>h</sup>	0	0				<u> </u>															0		0		0	0		0	0	0	0			
9/30/96 S	heenh		Sheend	Sheen	0	0																			0		NA		0	0		0	. 0	Sheen	0			
10/31/96 S	heenh		Sheenh	Sheen	0	0	0																		0.		0		0	0		0	0	0	0			
11/30/96 S	Sheen		NA	Sheen	NA	0																			0		NA		0	Sheen		. 0	0	Sheen <sup>h</sup>	0			

<sup>\*</sup> Solinst Model 121 oil/water interface probe. After 1/11/95, all wells were monitored using this probe when significant LNAPL is present.

<sup>&</sup>lt;sup>b</sup> No sheen noted when measurement device was placed in clean water, but water turned light brown after probing.

<sup>&</sup>lt;sup>c</sup> Orange/rust colored residue on probe.

d Globules.

<sup>&</sup>lt;sup>c</sup> Dark Phase.

<sup>&</sup>lt;sup>f</sup> Odor of decay.

<sup>&</sup>lt;sup>8</sup> 1000 mL of LNAPL were bailed from H10 at 10:45 am

h Slight sheen

NA = Not accessible.